


# Technical Bulletin

Subject: Instruction Guide & Service Manual QR Code Update

Date: November 7, 2024

Models Affected: **1060AW** - Instruction Guide SE-1060AW Rev B & Service Manual LT-2355 Rev B

The QR code links in the 1060AW Instruction Guide SE-1060AW Rev B and Service Manual LT-2355 Rev B are no longer active. The QR code located on the front cover of the instruction guide is still active and links to the PulmO2 main web site. Units with serial numbers prior to W2411060016S contain some QR codes that are no longer active. Below are the updated QR codes. Please make sure that any customers with units prior to the above serial number receive a copy of this bulletin, as a courtesy.



- en** Scan for Video Instructions
- es** Escanee para ver un video con las instrucciones
- fr** Rechercher des instructions vidéo



- en** Scan for Video Instructions
- es** Escanee para ver un video con las instrucciones
- fr** Rechercher des instructions vidéo

Thank you,  
Jamie Fitzgerald  
Technical Training Specialist

